


Restoration of printing cylinders on the offset printing equipment KOMORI LITHRONE S40P



During the offset printing the bolt has fallen to the working cylinder. There was a big and deep dent.



Defect after supersonic cleaning. Depth of defect is 3 mm



After cleaning metal which has filled defect has been applied. After metal spraying, grinding and polishing. During quality control of the performed work the raster has been printed. On the printed-out sheets of defects of the press e it is revealed.